

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Fig. 1  
(Prior Art)

COPY





Fig. 2  
(Prior Art)

COPY



COPY



No. 937 811E  
Engineer's Computation Pad

SAEDTLER®




Fig. 4A




Fig. 4B

COPY



No. 937 811E  
Engineer's Computation Pad

STAEDTLER®

Fig. 5





Fig. 6




COPY



No. 937 811E  
Engineer's Computation Pad

STAEDTLER®

Fig. 7



COPY

Fig. 8A




Fig. 8A




Fig. 8A

Fig. 8B

COPY






Fig 9A




Fig 9B




Fig 10A




Fig 10B





Fig. 11A




Fig. 11B





Fig. 11C

Fig. 12



COPY

Fig. 13




Fig. 14

